

## Case Study

### Contract

Contract number: 4300544693  
Contract Amount: \$ 99,970.00  
Contracting officer: Carol Durham  
717-783-3309  
[cdurham@pa.gov](mailto:cdurham@pa.gov)

### Project Location

Callen Run Road  
FOREST DISTRICT 08  
Jefferson COUNTY, PA

### Requirement

The Commonwealth of Pennsylvania, Department of Conservation and Natural Resources, Clear Creek State Forest required services to deliver, paver-place and roll approximately 2,710 tons of DSA (driving surface aggregate), to Callen Run Road.

### Challenges

- Delivery had to be at a rate of 6 trucks per hour.
- No material were to be delivered before 7:00 a.m. or after 3:00 p.m.
- All trucks must be driven by individuals capable of placing material in a paver.
- Delivery had to be continued on an uninterrupted basis.
- All material must be certified to not degrade the environment nor create health hazards.
- Aggregate must originate from a PennDOT qualified quarry source. Quarry source must be approved for the production of C2A, as listed in PennDOT Bulletin 14.

### Result

- GDI completed the work successfully fulfilling all the requirements.



## Key Factors Contributing to the Success

### • *Persistency*

Persistency is one of the main characteristics of GDI staff. They don't get tired and keep working till they reach the result.

### • *Quality Control*

Green dream was committed to supply the required specification at all costs. So it took every measure to search and find the best material available in the area and finally did achieve the goal.

### • *Management*

The key element of success in this project was close and momentary control over all aspects including time, quality , probabilities, possible delays and ... We did not fear to face the problems. Instead we had the determination to solve them.